Top Secret

25X1



DIRECTORATE OF INTELLIGENCE

Industrial Facilities (Non-Military)

Basic Imagery Interpretation Report

Iron and Steel Plants

North Korea

25X1

Top Secret

RCS 13/0021/71

DATE APRIL 1971

COPY 117

PAGES 11



Approved For Release 2008/05/20 : CIA-RDP79T00909A000700010014-4 TOP SECRET	RCS - 13/0021/71	25X 25X 25A
--	------------------	-------------------

CENTRAL INTELLIGENCE AGENCY Directorate of Intelligence Imagery Analysis Service

ABSTRACT

This report updates the Basic Imagery Interpretation Report on two iron and steel plants and two steel plants in North Korea. An initial report on a sponge iron plant is also included. These five plants comprise all of North Korea's known iron and steel production capability. This report covers the period from mid-1969 to late 1970.

Construction activity was observed at all of the previously reported plants. The major additions include a basic oxygen furnace section at the Chongjin Iron and Steel Plant Kimchaek and an air separation plant at the Songnim Iron and Steel Plant Hwanghae. A high level of activity was observed at all of the previously reported plants during the reporting period. Construction of the new Kiyang Sponge Iron Plant was started between November 1968 and October 1969. The plant was complete and operating when last observed in September 1970.

The four updates describe construction and level of activity and include more recent photography of the Chongjin and Kimchaek plants. The report on the new sponge iron plant includes an annotated photograph, mensuration of significant features, and a discussion of plant status and activity.

-1-	25X1 ^{25X1}
TOP SECRET	25X1




FIGURE 1. LOCATION MAP.

Approved For Release 2008/05/20 : CIA-RDP79T00909A0000700010014-4	25X125X
IUP SECKET	25X1

INTRODUCTION

This report includes studies on the following five plants: Chongjin Iron and Steel Plant Kimchaek, Kimchaek Steel Plant Songjin, Kiyang Sponge Iron Plant, Pyongyang Steel Plant Kangson, and Songnim Iron and Steel Plant Hwanghae.

The plants at Chongjin and Songjin are on the east coast, on the Sea of Japan. The other three plants, at Kangson, Kiyang and Songnim, are in the western part of the country, southwest of Pyongyang along the Taedong River (see Figure I). All five plants are served by road, rail, and water.

Four processes are used in North Korea to produce steel from pig iron or sponge iron: side-blown converter, open-hearth, electric, and basic oxygen. Air separation facilities at four of the plants produce oxygen for use in all of the various types of furnaces. Oxygen improves the quality of the steel by reducing impurities and shortening reduction time.

The approximate sizes and capacities of the blast furnaces were determined by comparing them with similar furnaces of known capacities in China. Blast furnaces are described as small (up to 200 tons a day), medium (200-700 tons a day), and large (700-1,300 tons a day).

Requirement	
COMIREX NO2 Support Number 421986	
Documen†	
CIA RCS - 13/0001/70, Iron and Steel Plants, North Korea, December 1969,	25X

25X1
TOP SECRET 25X1



oved For Release 2008/05/20 : CIA-RDP791	SECRET	25. 25.
	Lacuttov	
NSTALLATION OR ACTIVITY NAME	COUNTRY	
hongjin Iron and Steel Plant Kimcha TM COORDINATES GEOGRAPHIC COORDINATES	ek KN	25
2TEB632228 41-45-35N 129-45-24E		
USATC, Series 200, Sheet 0290	-15HL, 3rd ed, Aug 64, Scale 1:200,000	25.
ATEST IMAGERY USED	NEGATION DATE (If required)	
	NA	25.
BASI	C DESCRIPTION	
the southeast corner of the side-blocompleted by October 1969. A basic furnaces, was identified on November acility started just prior to Marchynen last observed in October 1970. Previously reported under constructive speared that work on them had stopp setween June 1969 and October 1970, were added at the air separation players added at the air separation players and october 1970. This building was previously level of activity was outlined on October 1970. On the latest players	oserved at the plant between September I otography, which was typical of most of	shing three te. cond shown y 969
operational blast furnaces, one basi	facilities were observed operating: the ric oxygen furnace, the side-blown convergeries, the iron ore sintering plant, the the power plant.	five ter
		25
	- 5-	0.5
		25 25



		TOP SEC	.KCI		
					25
NSTALLATION OF AC	TIVITY NAME			COUNTRY	
imchaek Steel	Plant Songj			KN	
2TEA 78047	40-41-46N 1				2
AP REFERENCE					
48RTG. USATC (SECRI		, Sheet M0290-	24HL, 4th ed, Apr 68, Sca	ale 1:200,000	2
ATEST IMAGERY USE			NEGATION DATE (If required)		
					_
			NA		2
		BASIC DE	SCRIPTION		
			the northern section of the date of the latest photo		!
revious repor	t. The addi	tion previous!	y reported under construc	ction at the	
orge/foundry o	complex (Fig	ure 3, Item 1)	was completed by Februar e rolling, blooming and s	ry 1970. Construct	ion
probable rol	ling mill (l	tem 3), previo	usly reported as an unide	entified building u	nder
		hanged. A new	unidentified building (1+om 1) moscuring	
noravimataly:	310 by 130 f				_
970. Initial	ground scar	eet, was exter ring for this	nally complete when last building was observed in	observed in Octobe March 1969. No	r
970. Initial	ground scar	eet, was exter ring for this	nally complete when last	observed in Octobe March 1969. No	r
970. Initial onstruction ac	ground scar ctivity was vel of activ	eet, was exter ring for this observed in th ity was observ	mally complete when last building was observed in e southern section of the ed at both sections of th	observed in Octobe March 1969. No e plant. ne plant from	r
970. Initial onstruction ac A high leveloper 1969 to	ground scar ctivity was vel of activ c October 19	eet, was exter ring for this observed in th ity was observ 70. On the la	mally complete when last building was observed in e southern section of the ed at both sections of the test imagery, which was t	observed in Octobe March 1969. No e plant. ne plant from typical of most	r
970. Initial onstruction act A high leveloctober 1969 to f the reference of the f	ground scar ctivity was vel of activ co October 19 ced coverage ive probable	eet, was exter ring for this observed in th ity was observ 70. On the la , the followin open-hearth f	mally complete when last building was observed in e southern section of the ed at both sections of the test imagery, which was t g facilities were observe urnaces, the electric fur	observed in Octobe March 1969. No e plant. The plant from typical of most ed operating:	г
970. Initial onstruction action and A high leveloctober 1969 to fithe reference of the fivolerge roll	ground scar ctivity was vel of activ co October 19 ced coverage ive probable ing mills, to	eet, was exter ring for this observed in th ity was observ 70. On the la , the followin open-hearth f wo forge/found	mally complete when last building was observed in e southern section of the ed at both sections of the test imagery, which was t g facilities were observe urnaces, the electric fur ry shops, one foundry, ar	observed in Octobe March 1969. No e plant. The plant from typical of mosted operating: Thace building, and one forge shop.	r
A high leveloper A high leveloper 1969 to fithe reference of the fivoleties of the fivoleties arge roll	ground scar ctivity was vel of activ co October 19 ced coverage ive probable ing mills, to	eet, was exter ring for this observed in th ity was observ 70. On the la , the followin open-hearth f wo forge/found	mally complete when last building was observed in e southern section of the ed at both sections of the test imagery, which was t g facilities were observe urnaces, the electric fur	observed in Octobe March 1969. No e plant. The plant from typical of mosted operating: Thace building, and one forge shop.	r
970. Initial construction actions A high leveloper 1969 to fithe reference of the fivo large roll	ground scar ctivity was vel of activ co October 19 ced coverage ive probable ing mills, to	eet, was exter ring for this observed in th ity was observ 70. On the la , the followin open-hearth f wo forge/found	mally complete when last building was observed in e southern section of the ed at both sections of the test imagery, which was t g facilities were observe urnaces, the electric fur ry shops, one foundry, ar	observed in Octobe March 1969. No e plant. The plant from typical of mosted operating: Thace building, and one forge shop.	
970. Initial onstruction action and A high leveloctober 1969 to fithe reference of the fivolerge roll	ground scar ctivity was vel of activ co October 19 ced coverage ive probable ing mills, to	eet, was exter ring for this observed in th ity was observ 70. On the la , the followin open-hearth f wo forge/found	mally complete when last building was observed in e southern section of the ed at both sections of the test imagery, which was t g facilities were observe urnaces, the electric fur ry shops, one foundry, ar	observed in Octobe March 1969. No e plant. The plant from typical of mosted operating: Thace building, and one forge shop.	
970. Initial construction actions A high leveloper 1969 to fithe reference of the fivo large roll	ground scar ctivity was vel of activ co October 19 ced coverage ive probable ing mills, to	eet, was exter ring for this observed in th ity was observ 70. On the la , the followin open-hearth f wo forge/found	mally complete when last building was observed in e southern section of the ed at both sections of the test imagery, which was t g facilities were observe urnaces, the electric fur ry shops, one foundry, ar	observed in Octobe March 1969. No e plant. The plant from typical of mosted operating: Thace building, and one forge shop.	
A high leveloper 1969 to the reference of the food large roll	ground scar ctivity was vel of activ co October 19 ced coverage ive probable ing mills, to	eet, was exter ring for this observed in th ity was observ 70. On the la , the followin open-hearth f wo forge/found	mally complete when last building was observed in e southern section of the ed at both sections of the test imagery, which was t g facilities were observe urnaces, the electric fur ry shops, one foundry, ar	observed in Octobe March 1969. No e plant. The plant from typical of mosted operating: Thace building, and one forge shop.	
970. Initial construction action and A high leveloper 1969 to fithe reference of the fivolarge roll	ground scar ctivity was vel of activ co October 19 ced coverage ive probable ing mills, to	eet, was exter ring for this observed in th ity was observ 70. On the la , the followin open-hearth f wo forge/found	mally complete when last building was observed in e southern section of the ed at both sections of the test imagery, which was t g facilities were observe urnaces, the electric fur ry shops, one foundry, ar	observed in Octobe March 1969. No e plant. The plant from typical of mosted operating: Thace building, and one forge shop.	
970. Initial construction action and A high leveloper 1969 to fithe reference of the fivolarge roll	ground scar ctivity was vel of activ co October 19 ced coverage ive probable ing mills, to	eet, was exter ring for this observed in th ity was observ 70. On the la , the followin open-hearth f wo forge/found	mally complete when last building was observed in e southern section of the ed at both sections of the test imagery, which was t g facilities were observe urnaces, the electric fur ry shops, one foundry, ar	observed in Octobe March 1969. No e plant. The plant from typical of mosted operating: Thace building, and one forge shop.	
970. Initial construction actions A high leveloper 1969 to fithe reference of the fivo large roll	ground scar ctivity was vel of activ co October 19 ced coverage ive probable ing mills, to	eet, was exter ring for this observed in th ity was observ 70. On the la , the followin open-hearth f wo forge/found	mally complete when last building was observed in e southern section of the ed at both sections of the test imagery, which was t g facilities were observe urnaces, the electric fur ry shops, one foundry, ar	observed in Octobe March 1969. No e plant. The plant from typical of mosted operating: Thace building, and one forge shop.	
970. Initial construction actions A high leveloper 1969 to fithe reference of the fivo large roll	ground scar ctivity was vel of activ co October 19 ced coverage ive probable ing mills, to	eet, was exter ring for this observed in th ity was observ 70. On the la , the followin open-hearth f wo forge/found	mally complete when last building was observed in e southern section of the ed at both sections of the test imagery, which was t g facilities were observe urnaces, the electric fur ry shops, one foundry, ar	observed in Octobe March 1969. No e plant. The plant from typical of mosted operating: Thace building, and one forge shop.	
970. Initial construction actions A high leveloper 1969 to fithe reference of the fivo large roll	ground scar ctivity was vel of activ co October 19 ced coverage ive probable ing mills, to	eet, was exter ring for this observed in th ity was observ 70. On the la , the followin open-hearth f wo forge/found	mally complete when last building was observed in e southern section of the ed at both sections of the test imagery, which was t g facilities were observe urnaces, the electric fur ry shops, one foundry, ar	observed in Octobe March 1969. No e plant. The plant from typical of mosted operating: Thace building, and one forge shop.	
970. Initial construction action and A high leveloper 1969 to fithe reference of the fivolarge roll	ground scar ctivity was vel of activ co October 19 ced coverage ive probable ing mills, to	eet, was exter ring for this observed in th ity was observ 70. On the la , the followin open-hearth f wo forge/found	mally complete when last building was observed in e southern section of the ed at both sections of the test imagery, which was t g facilities were observe urnaces, the electric fur ry shops, one foundry, ar	observed in Octobe March 1969. No e plant. The plant from typical of mosted operating: Thace building, and one forge shop.	
970. Initial onstruction action and A high levictober 1969 to fithe reference of the fivo large roll	ground scar ctivity was vel of activ co October 19 ced coverage ive probable ing mills, to	eet, was exter ring for this observed in th ity was observ 70. On the la , the followin open-hearth f wo forge/found	mally complete when last building was observed in e southern section of the ed at both sections of the test imagery, which was t g facilities were observe urnaces, the electric fur ry shops, one foundry, ar	observed in Octobe March 1969. No e plant. The plant from typical of mosted operating: Thace building, and one forge shop.	
970. Initial onstruction action and A high levictober 1969 to fithe reference of the fivo large roll	ground scar ctivity was vel of activ co October 19 ced coverage ive probable ing mills, to	eet, was exter ring for this observed in th ity was observ 70. On the la , the followin open-hearth f wo forge/found	mally complete when last building was observed in e southern section of the ed at both sections of the test imagery, which was t g facilities were observe urnaces, the electric fur ry shops, one foundry, ar	observed in Octobe March 1969. No e plant. The plant from typical of mosted operating: Thace building, and one forge shop.	
970. Initial onstruction action and A high levictober 1969 to fithe reference of the fivo large roll	ground scar ctivity was vel of activ co October 19 ced coverage ive probable ing mills, to	eet, was exter ring for this observed in th ity was observ 70. On the la , the followin open-hearth f wo forge/found	mally complete when last building was observed in e southern section of the ed at both sections of the test imagery, which was t g facilities were observe urnaces, the electric fur ry shops, one foundry, ar	observed in Octobe March 1969. No e plant. The plant from typical of mosted operating: Thace building, and one forge shop.	
970. Initial onstruction aconstruction aconstruction aconstruction aconstruction and the first the reference of the fivo large roll	ground scar ctivity was vel of activ co October 19 ced coverage ive probable ing mills, to	eet, was exter ring for this observed in th ity was observ 70. On the la , the followin open-hearth f wo forge/found	mally complete when last building was observed in e southern section of the ed at both sections of the test imagery, which was t g facilities were observe urnaces, the electric fur ry shops, one foundry, ar	observed in Octobe March 1969. No e plant. The plant from typical of mosted operating: Thace building, and one forge shop.	
970. Initial onstruction aconstruction aconstruction aconstruction aconstruction and the firm of the reference of the five large roll	ground scar ctivity was vel of activ co October 19 ced coverage ive probable ing mills, to	eet, was exter ring for this observed in th ity was observ 70. On the la , the followin open-hearth f wo forge/found	mally complete when last building was observed in e southern section of the ed at both sections of the test imagery, which was t g facilities were observe urnaces, the electric fur ry shops, one foundry, ar	observed in Octobe March 1969. No e plant. The plant from typical of mosted operating: Thace building, and one forge shop.	
970. Initial onstruction aconstruction aconstruction aconstruction aconstruction and the firm of the reference of the five large roll	ground scar ctivity was vel of activ co October 19 ced coverage ive probable ing mills, to	eet, was exter ring for this observed in th ity was observ 70. On the la , the followin open-hearth f wo forge/found	mally complete when last building was observed in e southern section of the ed at both sections of the test imagery, which was t g facilities were observe urnaces, the electric fur ry shops, one foundry, ar	observed in Octobe March 1969. No e plant. The plant from typical of mosted operating: Thace building, and one forge shop.	25.

-7-






FIGURE 4. KIYANG SPONGE IRON PLANT,

25X1

	Key to	Annotations	
ltem	Description	Dimensions (Ft)	Roof Cover (Sq Ft)
1	Sponge Iron Separation and Shipping Building	350 x 85	29,750
2	Rotary Kilns (2)		-
3	Rotary Kilns (2)	240 × 10	
4	Ore Preparation and Mixing Facilities	-	-
5	Ore Receiving Building	460 × 85	39,100
6	Probable Producer Gas Plant	-	-

25X1,

-8-TOP SECRET 25X1 25X1

MAP REFERENCE ISNOO. USATC, Series 200, Sheet MO380-7HL. 4th ed. (SECRET	BE NUMBER None Nov 68. Scal	COMIREX NO. None	NIETB NO. None	25X′
ISYD212075 38-53-11N 125-33-50E MAP REFERENCE ISNOO. USATC, Series 200, Sheet MO380-7HL. 4th ed. (SECRET	None Nov 68. Scal	None	None	20/(1
(SECRET,		e 1:200.000		,
		e 1:200.000	1	
	ATE (If required)		,	25X1
THE STREET THE STREET STREET	(I E (II required)			. ∠5X1
			٦	OEV4
				25X1
	**			
BASIC DESCRIPTION				
,200 by 2,800 feet. The plant will have direct achen a wharf under construction, 0.5 nm to the sout purs are completed.	heast, and th	ne connectir	ng rail	
This plant probably employs the Krupp-Renn process high-silica ore. The primary product of the sprimary product of the sprimar	his process i steel plant. ing facilitie	s an iron no The plant s, four rota	odule contains arv kilns	,
Construction of this plant started between Novit was complete and operating when last observed in	vember 1968 a n September 1	nd October 970.	1969.	
REFERENCES				
THE CITETOES				25X1
ocumen†				

^{25X1}_{25X1} 25X1

TOP SECRET

oved For Release 2008/05/20 : CIA-RDP79T009		25X1
TOP SEC	KET	25X1
INSTALLATION OR ACTIVITY NAME		COUNTRY
INSTALLATION OF ACTIVITY WANTE		
Pyongyang Steel Plant Kangson		KN
UTM COORDINATES GEOGRAPHIC COORDINATES		25X1
SYD240 3 38-55- 4N 25-35-0 E		
ISNOO. USATC, Series 200, Sheet M0380-7H	HL. 4th ed. Nov 68. Scale 1:	:200.000 (SECRET/
00/105, 00/105 200, 01/007 1/0007		25X1
LATEST IMAGERY USED	NEGATION DATE (If required)	
	i	25X1
	NA NA	
BQ210 L	DESCRIPTION	
<i>B</i> /1510 E	JESOKII I TON	
Construction has been observed at t august 1969, the date of the latest phot		
addition, previously observed under cons		
was complete in March 1970. A large sto		
has been constructed next to the two nor inished between October 1969 and April		
storage yards were extended between Apri		v
A high level of activity was observ	ved at the plant on all pho	tographic missions
from October 1969 to September 1970. No	smoke was seen emanating	from the new
electric furnace building. On imagery o were observed in small numbers adjacent	of April and September 1970 to the building. This ind	, however, ingots icates the new
electric furnaces are probably operating		
		25X1

METALL ATION OF ACTUUM			
NSTALLATION OR ACTIVITY	NAME	COUNTRY	
ongnim Iron and Ste	el Plant Hwandhae	KN	
TM COORDINATES GEOGR	RAPHIC COORDINATES		25X1
ISYC287912 38-4 AP REFERENCE	4-22N 125-37-08E		
SNOO. <u>USATC. Series</u>	200. Sheet M0380-7	HL, 4th ed, Nov 68, Scale 1:200,000 (SECI	RET/ 25X1
ATEST IMAGERY USED		NEGATION DATE (If required)	
		N/A	2
		NA NA	
	BASIC D	ESCRIPTION	
as complete in Nove nder construction, n two others, which he possible iron or	ember 1969. The two have been completed will probably be l re sintering plant h	ility. A pipeline connects the two facing and under construction in January 1968 as small blast furnaces, previously observed and appear to be operational. Constructing blast furnaces, appears to have stoward either been completed or is nearing contracting of the contraction.	and it ed tion pped. om-
as complete in Nove ander construction, in two others, which he possible iron or letion. It did not here are possibly sacility rather than A high level of etween July 1969 and here observed operate	mber 1969. The two have been completed will probably be I re sintering plant he appear to be operative open-hearth furn five as previously activity was obserted April 1970. On thing: five of the second complete of the second comp	erved under construction in January 1968 as small blast furnaces, previously observed and appear to be operational. Constructuring blast furnaces, appears to have stowas either been completed or is nearing cuting. Continuing analysis revealed that paces in the probable furnace and rolling	and it ed tion pped. om- ry ties
as complete in Nove ander construction, in two others, which he possible iron or letion. It did not here are possibly sacility rather than A high level of etween July 1969 and here observed operate	mber 1969. The two have been completed will probably be I re sintering plant he appear to be operative open-hearth furn five as previously activity was obserted April 1970. On thing: five of the second complete of the second comp	erved under construction in January 1968 as small blast furnaces, previously observed and appear to be operational. Constructions arge blast furnaces, appears to have stowass either been completed or is nearing conting. Continuing analysis revealed that faces in the probable furnace and rolling reported. The provided the plant on the referenced image the latest coverage, the following facilities are presented in the proportional blast furnaces, four of	and it ed tion pped. om- ry ties the
as complete in Nove nder construction, n two others, which he possible iron or letion. It did not here are possibly sacility rather than A high level of etween July 1969 and ere observed operation.	mber 1969. The two have been completed will probably be I re sintering plant he appear to be operative open-hearth furn five as previously activity was obserted April 1970. On thing: five of the second complete of the second comp	erved under construction in January 1968 as small blast furnaces, previously observed and appear to be operational. Constructions arge blast furnaces, appears to have stowass either been completed or is nearing conting. Continuing analysis revealed that faces in the probable furnace and rolling reported. The provided the plant on the referenced image the latest coverage, the following facilities are presented in the proportional blast furnaces, four of	and it ed tion pped. om- ry ties
as complete in Nove nder construction, n two others, which he possible iron or letion. It did not here are possibly sacility rather than A high level of etween July 1969 and ere observed operation.	mber 1969. The two have been completed will probably be I re sintering plant he appear to be operative open-hearth furn five as previously activity was obserted April 1970. On thing: five of the second complete of the second comp	erved under construction in January 1968 as small blast furnaces, previously observed and appear to be operational. Constructions arge blast furnaces, appears to have stowass either been completed or is nearing conting. Continuing analysis revealed that faces in the probable furnace and rolling reported. The provided the plant on the referenced image the latest coverage, the following facilities are presented in the proportional blast furnaces, four of	and it ed tion pped. om- ry ties the
as complete in Nove nder construction, n two others, which he possible iron or letion. It did not here are possibly sacility rather than A high level of etween July 1969 and ere observed operation.	mber 1969. The two have been completed will probably be I re sintering plant he appear to be operative open-hearth furn five as previously activity was obserted April 1970. On thing: five of the second complete of the second comp	erved under construction in January 1968 as small blast furnaces, previously observed and appear to be operational. Constructions arge blast furnaces, appears to have stowass either been completed or is nearing conting. Continuing analysis revealed that faces in the probable furnace and rolling reported. The provided the plant on the referenced image the latest coverage, the following facilities are presented in the proportional blast furnaces, four of	and it ed tion pped. om- ry ties the
as complete in Nove nder construction, n two others, which he possible iron or letion. It did not here are possibly sacility rather than A high level of etween July 1969 and ere observed operation.	mber 1969. The two have been completed will probably be I re sintering plant he appear to be operative open-hearth furn five as previously activity was obserted April 1970. On thing: five of the second complete of the second comp	erved under construction in January 1968 as small blast furnaces, previously observed and appear to be operational. Constructions arge blast furnaces, appears to have stowass either been completed or is nearing conting. Continuing analysis revealed that faces in the probable furnace and rolling reported. The provided the plant on the referenced image the latest coverage, the following facilities are presented in the proportional blast furnaces, four of	and it ed tion pped. om- ry ties the
as complete in Nove nder construction, n two others, which he possible iron or letion. It did not here are possibly sacility rather than A high level of etween July 1969 and ere observed operation.	mber 1969. The two have been completed will probably be I re sintering plant he appear to be operative open-hearth furn five as previously activity was obserted April 1970. On thing: five of the second complete of the second comp	erved under construction in January 1968 as small blast furnaces, previously observed and appear to be operational. Constructions arge blast furnaces, appears to have stowass either been completed or is nearing conting. Continuing analysis revealed that faces in the probable furnace and rolling reported. The provided the plant on the referenced image the latest coverage, the following facilities are presented in the proportional blast furnaces, four of	and it ed tion pped. om- ry ties the
as complete in Nove nder construction, n two others, which he possible iron or letion. It did not here are possibly sacility rather than A high level of etween July 1969 and ere observed operation.	mber 1969. The two have been completed will probably be I re sintering plant he appear to be operative open-hearth furn five as previously activity was obserted April 1970. On thing: five of the second complete of the second comp	erved under construction in January 1968 as small blast furnaces, previously observed and appear to be operational. Constructions arge blast furnaces, appears to have stowass either been completed or is nearing conting. Continuing analysis revealed that faces in the probable furnace and rolling reported. The provided the plant on the referenced image the latest coverage, the following facilities are presented in the proportional blast furnaces, four of	and it ed tion pped. om- ry ties the
as complete in Nove ander construction, in two others, which he possible iron or letion. It did not here are possibly sacility rather than A high level of etween July 1969 and here observed operate	mber 1969. The two have been completed will probably be I re sintering plant he appear to be operative open-hearth furn five as previously activity was obserted April 1970. On thing: five of the second complete of the second comp	erved under construction in January 1968 as small blast furnaces, previously observed and appear to be operational. Constructions arge blast furnaces, appears to have stowass either been completed or is nearing conting. Continuing analysis revealed that faces in the probable furnace and rolling reported. The provided the plant on the referenced image the latest coverage, the following facilities are presented in the proportional blast furnaces, four of	and it ed tion pped. om- ry ties the
as complete in Nove nder construction, n two others, which he possible iron or letion. It did not here are possibly sacility rather than A high level of etween July 1969 and ere observed operate.	mber 1969. The two have been completed will probably be I re sintering plant he appear to be operative open-hearth furn five as previously activity was obserted April 1970. On thing: five of the second complete of the second comp	erved under construction in January 1968 as small blast furnaces, previously observed and appear to be operational. Constructions arge blast furnaces, appears to have stowass either been completed or is nearing conting. Continuing analysis revealed that faces in the probable furnace and rolling reported. The provided the plant on the referenced image the latest coverage, the following facilities are presented in the proportional blast furnaces, four of	and it ed tion pped. om- ry ties the
as complete in Nove nder construction, n two others, which he possible iron or letion. It did not here are possibly sacility rather than A high level of etween July 1969 and ere observed operate.	mber 1969. The two have been completed will probably be I re sintering plant he appear to be operative open-hearth furn five as previously activity was obserted April 1970. On thing: five of the second complete of the second comp	erved under construction in January 1968 as small blast furnaces, previously observed and appear to be operational. Constructions arge blast furnaces, appears to have stowass either been completed or is nearing conting. Continuing analysis revealed that faces in the probable furnace and rolling reported. The provided the plant on the referenced image the latest coverage, the following facilities are presented in the proportional blast furnaces, four of	and it ed tion pped. om- ry ties the
as complete in Nove nder construction, n two others, which he possible iron or letion. It did not here are possibly sacility rather than A high level of etween July 1969 and ere observed operate.	mber 1969. The two have been completed will probably be I re sintering plant he appear to be operative open-hearth furn five as previously activity was obserted April 1970. On thing: five of the second complete of the second comp	erved under construction in January 1968 as small blast furnaces, previously observed and appear to be operational. Constructions arge blast furnaces, appears to have stowass either been completed or is nearing conting. Continuing analysis revealed that faces in the probable furnace and rolling reported. The provided the plant on the referenced image the latest coverage, the following facilities are presented in the proportional blast furnaces, four of	and it ed tion pped. om- ry ties the
as complete in Nove nder construction, n two others, which he possible iron or letion. It did not here are possibly sacility rather than A high level of etween July 1969 and ere observed operation.	mber 1969. The two have been completed will probably be I re sintering plant he appear to be operative open-hearth furn five as previously activity was obserted April 1970. On thing: five of the second complete of the second comp	erved under construction in January 1968 as small blast furnaces, previously observed and appear to be operational. Constructions arge blast furnaces, appears to have stowass either been completed or is nearing conting. Continuing analysis revealed that faces in the probable furnace and rolling reported. The provided the plant on the referenced image the latest coverage, the following facilities are presented in the proportional blast furnaces, four of	and it ed tion pped. om- ry ties the

Approved For Release 2008/05/20 : CIA-RDP79T00909A000700010014-4

Top Secret